


10017254, 124401

FIG. 1






FIG. 3




FIG. 4







FIG. 5



100 *Journal of Health Politics*

FIG. 6A

Measurement of difference in height of left and right flanges of power collecting plate

**FIG. 6B** Inspection for fillet number**FIG. 6C**

Measurement of thickness of polar plate





FIG. 7A

Measurement of fillet height



10017254-121401

FIG. 7B

Inspection of fillet shape




FIG. 8






FIG. 9






FIG. 10

FIG. 11A




FIG. 11B




FIG. 12

